



- 1 requires bi-directional movement of input
- 2 requires detent to lock the lens in "in" position
- 3 high friction and wear in slot