



Instantaneous Screw Axis (ISA)

Finite Screw Axis (Finite Helical Axis - FHA)

Three-Dimensional Kennedy-Aronholdt Theroem

ISAs between three bodies share a common perpendicular

Axode